

Release Date: 10/22/19

Doc. #: 200004

BH SENS New OER Sensor Advisory



OER Part #: OER500

OE Supplier: Pacific (H6)

At BH SENS we are committed to 100% coverage. That's why we started our Original Equipment Replacement Program, providing the exact same part used in the factory. For more information on this or any other sensor, including pricing options, please contact your BH SENS account manager, or call our technical support hotline at +1 855-483-8767



2007 - 2013 Acura MDX

Sub-Models:

N/a

Covered by UVS:

No



2007 - 2012 Acura RDX

Sub-Models:

N/a

Covered by UVS:

No



2007 - 2013 Acura TSX

Sub-Models:

N/a

Covered by UVS:

No

For more extensive and up-to-date information check our product finder at products.intellisens.com/

The information contained in this flier is based on information provided by the Huf Baolong Electronics and Third Parties, in particular vehicle manufacturers, TPMS or component manufacturers, TPMS equipment manufacturers and tool manufacturers. Huf Baolong Electronics has not verified in any respect the accuracy or completeness of such information at the time of this publication.

Huf Baolong Electronics North America Corp.

9020 W. Dean Road Milwaukee, WI 53224, USA

+1-414-365-8173 +1-414-365-8158

+1-414-365-8175

www.Intellisens.com

DRIVING TPMS INNOVATION

It Just Makes SENS