

# BH SENS New OER Sensor Advisory



**OER Part #:** OER501

**OE Supplier:** Pacific (T5)

At BH SENS we are committed to 100% coverage. That's why we started our Original Equipment Replacement Program, providing the exact same part used in the factory. For more information on this or any other sensor, including pricing options, please contact your BH SENS account manager, or call our technical support hotline at +1 855-483-8767



## 2013 - 2018 Lexus ES

**Sub-Models:**

300h, 350

**Covered by UVS:**

No



## 2013 - EOP Lexus GS

**Sub-Models:**

200t, 350, 450h

**Covered by UVS:**

No



## 2014 - EOP Lexus IS

**Sub-Models:**

200t, 250, 300, 350

**Covered by UVS:**

No



## 2013 - EOP Lexus LS

**Sub-Models:**

460, 600h

**Covered by UVS:**

No



## 2015 Toyota Land Cruiser

**Sub-Models:**

N/a

**Covered by UVS:**

No

\* Coverage not shown: Lexus GSF (2016-EOP); Lexus GX 460 (2019-EOP); Lexus NX 200t, 300, & 300h (2015-EOP); Lexus RC F (2015-EOP), Lexus RC 200t, 300, 350 (2015-EOP).

For more extensive and up-to-date information check our product finder at [products.intellisens.com/](http://products.intellisens.com/)

The information contained in this flier is based on information provided by the Huf Baolong Electronics and Third Parties, in particular vehicle manufacturers, TPMS or component manufacturers, TPMS equipment manufacturers and tool manufacturers. Huf Baolong Electronics has not verified in any respect the accuracy or completeness of such information at the time of this publication.