

BH SENS New OER Sensor Advisory



OER Part #: OER502

OE Supplier: Pacific (T6)

At BH SENS we are committed to 100% coverage. That's why we started our Original Equipment Replacement Program, providing the exact same part used in the factory. For more information on this or any other sensor, including pricing options, please contact your BH SENS account manager, or call our technical support hotline at +1 855-483-8767



2016 - EOP Toyota Avalon

Sub-Models:

N/a

Covered by UVS:

Yes



2015 - EOP Toyota Camry

Sub-Models:

N/a

Covered by UVS:

Yes



2019 - EOP Lexus ES 350

Sub-Models:

N/a

Covered by UVS:

Yes



2015 - EOP Lexus RX

Sub-Models: 350 (US & Japan), 450h

Covered by UVS:

Yes



2016 - EOP Toyota Tacoma

Sub-Models:

N/A

Covered by UVS:

Yes

* Coverage not shown: Toyota C-HR (2018-EOP); Toyota Land Cruiser (2016-EOP); Lexus GX 460 (2016-2018); Lexus LC 500 & 500h (2018-EOP); Lexus LX 570 (2016-EOP); Lexus UX 200 (2019-EOP).

For more extensive and up-to-date information check our product finder at products.intellisens.com/

The information contained in this flier is based on information provided by the Huf Baolong Electronics and Third Parties, in particular vehicle manufacturers, TPMS or component manufacturers, TPMS equipment manufacturers and tool manufacturers. Huf Baolong Electronics has not verified in any respect the accuracy or completeness of such information at the time of this publication.