

BH SENS New OER Sensor Advisory



OER Part #: OER503

OE Supplier: Pacific (T17)

At BH SENS we are committed to 100% coverage. That's why we started our Original Equipment Replacement Program, providing the exact same part used in the factory. For more information on this or any other sensor, including pricing options, please contact your BH SENS account manager, or call our technical support hotline at +1 855-483-8767



2011-2015 Toyota Yaris

Sub-Models: Hatchback & Sedan

Covered by UVS: Yes



2012-2026 Toyota Prius

Sub-Models: C, CUV, & V

Covered by UVS: Yes



2013-2024 Toyota RAV4

Sub-Models: Japan & US Models

Covered by UVS: Yes



2016 - EOP Toyota Mirai

Sub-Models: N/a

Covered by UVS: Yes



2019 - EOP Toyota Corolla

Sub-Models: N/a

Covered by UVS: Yes

* Not shown, 2016 Scion iM

For more extensive and up-to-date information check our product finder at products.intellisens.com/

The information contained in this flier is based on information provided by the Huf Baolong Electronics and Third Parties, in particular vehicle manufacturers, TPMS or component manufacturers, TPMS equipment manufacturers and tool manufacturers. Huf Baolong Electronics has not verified in any respect the accuracy or completeness of such information at the time of this publication.