

Huf Group

Your Preferred Partner for Tire Pressure Monitoring Systems



TPMS Application Guide

Edition 2-2015

...the **intelligent**
touch to cars.

Table of Contents

Applications Listings	3-12
OE Replacement Sensors	13-17
Huf Intellisens Universal Sensors	18-19
Valves	20
Accessories	21
OE Interchange	22-23



Huf Warranty: All products sold are warranted against defects in workmanship and material under normal use and service for the earlier of (1) a period of three years from the date of installation, or (2) a period of five years from the date of sale to the Huf Distributor. Huf will either repair or replace any product which fails during this period. This warranty does not include any labor for the repair or replacement of the product.

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Acura				
CSX	2008-2011	UVS3010/UVS3011		315 MHz
ILX	2013-2015	UVS3010/UVS3011		315 MHz
Aston Martin				
DB9	2010-2015	UVS2000	RDE011V21	433 MHz
DB9	2010-2015		RDE022V21	315 MHz
DBS	2008-2012	UVS2000	RDE011V21	433 MHz
DBS	2008-2012		RDE022V21	315 MHz
Rapide	2010-2011	UVS2000	RDE011V21	433 MHz
Rapide	2010-2011		RDE022V21	315 MHz
V12 Vantage	2013-2015	UVS2000	RDE011V21	433 MHz
V12 Vantage	2013-2015		RDE022V21	315 MHz
V8 Vantage	2010-2015	UVS2000	RDE011V21	433 MHz
V8 Vantage	2010-2015		RDE022V21	315 MHz
Vanquish	2012-2015		RDE022V21	315 MHz
Vanquish	2013-2015	UVS2000	RDE011V21	433 MHz
Virage	2012	UVS2000	RDE011V21	433 MHz
Audi				
A3	2006-2009	UVS3010/UVS3011		315 MHz
A4	2009	UVS3010/UVS3011		315 MHz
A4	2002-2008	UVS2000	RDE011V21	433 MHz
A5	2008-2009	UVS3010/UVS3011		315 MHz
A6	2004	UVS2000	RDE011V21	433 MHz
A6	2005		RDE001V21	433 MHz
A6	2005	UVS2000	RDE011V21	433 MHz
A6	2000-2003		RDE001V21	433 MHz
A6	2000-2004		RDE004V21	315 MHz
A6	2005-2008		RDE022V21	315 MHz
A6	2006-2009	UVS2000	RDE011V21	433 MHz
A8	2000-2009		RDE001V21	433 MHz
A8	2000-2009		RDE004V21	315 MHz
Allroad Quattro	2001-2005		RDE001V21	433 MHz
Allroad Quattro	2001-2005		RDE004V21	315 MHz
Q7	2005-2009	UVS2000	RDE011V21	433 MHz
R8	2008-2015	UVS2000	RDE011V21	433 MHz
RS4	2007-2009	UVS2000	RDE011V21	433 MHz
RS6	2003		RDE001V21	433 MHz
RS6	2003		RDE004V21	315 MHz
RS7	2014-2015	UVS2000	RDE011V21	433 MHz
S4	2002-2009	UVS2000	RDE011V21	433 MHz
S4	2005-2007		RDE022V21	315 MHz
S5	2008-2009	UVS3010/UVS3011		315 MHz
S6	2004-2009	UVS2000	RDE011V21	433 MHz
S6	2004-2008		RDE022V21	315 MHz
S8	1999-2009		RDE001V21	433 MHz
S8	1999-2009		RDE004V21	315 MHz
TT	2006-2009	UVS3010/UVS3011		315 MHz
Bentley				
Arnage	2008-2009	UVS2000	RDE011V21	433 MHz
Azure	2007-2009	UVS2000	RDE011V21	433 MHz
Brooklands	2008-2011	UVS2000	RDE011V21	433 MHz
Continental	2003-2005		RDE001V21	433 MHz
Continental	2005-2015	UVS2000	RDE011V21	433 MHz
Flying Spur	2006-2015	UVS2000	RDE011V21	433 MHz
Mulsanne	2011-2016	UVS2000	RDE011V21	433 MHz
BMW				
128i	2008-2010	UVS2000	RDE008V21	433 MHz
128i	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
135i	2008-2010	UVS2000	RDE008V21	433 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
135i	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
135is	2013	UVS4010/UVS4011	RDE012V21	433 MHz
228i	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
320i	2013-2014	UVS4010/UVS4011	RDE017V21	433 MHz
320i	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
323Ci	2000		RDE004V21	315 MHz
323Ci	2000		RDE002V21	433 MHz
323i	1999-2000		RDE004V21	315 MHz
323i	1999-2000		RDE002V21	433 MHz
323is	1999		RDE004V21	315 MHz
323is	1999		RDE002V21	433 MHz
325Ci	2001-2005		RDE004V21	315 MHz
325Ci	2001-2006		RDE002V21	433 MHz
325i	2001-2005		RDE004V21	315 MHz
325i	2001-2006		RDE002V21	433 MHz
325xi	2001-2005		RDE004V21	315 MHz
325xi	2001-2006		RDE002V21	433 MHz
328Ci	2000		RDE004V21	315 MHz
328Ci	2000		RDE002V21	433 MHz
328d	2014		RDE017V21	433 MHz
328d	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
328i	2012	UVS4010/UVS4011	RDE017V21	433 MHz
328i	1999-2000	UVS4010/UVS4011	RDE004V21	315 MHz
328i	1999-2000		RDE002V21	433 MHz
328i	2007-2009	UVS2000	RDE008V21	433 MHz
328i	2010-2012	UVS4010/UVS4011	RDE012V21	433 MHz
328i	2013-2014	UVS4010/UVS4011	RDE017V21	433 MHz
328i	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
328is	1999		RDE004V21	315 MHz
328is	1999		RDE002V21	433 MHz
328xi	2007-2008	UVS2000	RDE008V21	433 MHz
330Ci	2001-2005		RDE004V21	315 MHz
330Ci	2001-2006		RDE002V21	433 MHz
330i	2001-2004		RDE004V21	315 MHz
330i	2001-2004		RDE002V21	433 MHz
330xi	2001-2005		RDE004V21	315 MHz
330xi	2001-2006		RDE002V21	433 MHz
335d	2009	UVS2000	RDE008V21	433 MHz
335d	2012	UVS4010/UVS4011	RDE017V21	433 MHz
335d	2009-2012	UVS4010/UVS4011	RDE012V21	433 MHz
335i	2012	UVS4010/UVS4011	RDE017V21	433 MHz
335i	2007-2009	UVS2000	RDE008V21	433 MHz
335i	2009-2012	UVS4010/UVS4011	RDE012V21	433 MHz
335i	2013-2014	UVS4010/UVS4011	RDE017V21	433 MHz
335i	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
335is	2012	UVS4010/UVS4011	RDE017V21	433 MHz
335is	2013	UVS4010/UVS4011	RDE017V21	433 MHz
335is	2011-2012	UVS4010/UVS4011	RDE012V21	433 MHz
335xi	2007-2008	UVS2000	RDE008V21	433 MHz
428i	2014	UVS4010/UVS4011	RDE017V21	433 MHz
428i	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
435i	2014	UVS4010/UVS4011	RDE017V21	433 MHz
435i	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
525i	2001-2002		RDE004V21	315 MHz
525i	2005-2005		RDE002V21	433 MHz
525i	2006-2007	UVS2000	RDE008V21	433 MHz
525xi	2006-2007	UVS2000	RDE008V21	433 MHz
528i	2014	UVS4010/UVS4011	RDE012V21	433 MHz
528i	1997-2000		RDE004V21	315 MHz

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
528i	2008-2010	UVS2000	RDE008V21	433 MHz
528i	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
528i	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
528xi	2008	UVS2000	RDE008V21	433 MHz
530i	2001-2002		RDE004V21	315 MHz
530i	2002-2005		RDE002V21	433 MHz
530i	2006-2007	UVS2000	RDE008V21	433 MHz
530xi	2006-2007	UVS2000	RDE008V21	433 MHz
535d	2014	UVS4010/UVS4011	RDE012V21	433 MHz
535d	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
535i	2014	UVS4010/UVS4011	RDE012V21	433 MHz
535i	2008-2010	UVS2000	RDE008V21	433 MHz
535i	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
535i	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
535xi	2008	UVS2000	RDE008V21	433 MHz
540i	1997-2002		RDE004V21	315 MHz
540i	2002-2003		RDE002V21	433 MHz
545i	2004-2005		RDE002V21	433 MHz
550i	2014	UVS4010/UVS4011	RDE012V21	433 MHz
550i	2006-2010	UVS2000	RDE008V21	433 MHz
550i	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
550i	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
640i	2012-2014	UVS4010/UVS4011	RDE012V21	433 MHz
640i	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
650i	2006-2010	UVS2000	RDE008V21	433 MHz
650i	2012-2014	UVS4010/UVS4011	RDE012V21	433 MHz
650i	2014-2016	UVS4010/UVS4011	RDE017V21	433 MHz
740i	1997-2001		RDE004V21	315 MHz
740i	1998-2001		RDE002V21	433 MHz
740i	2011-2014	UVS4010/UVS4011	RDE012V21	433 MHz
740i	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
740iL	1997-2001		RDE004V21	315 MHz
740iL	1998-2001		RDE004V21	315 MHz
740Ld	2015	UVS4010/UVS4011	RDE017V21	433 MHz
740Li	2011-2014	UVS4010/UVS4011	RDE012V21	433 MHz
740Li	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
745i	2002		RDE004V21	315 MHz
745i	2002-2005		RDE002V21	433 MHz
745Li	2002		RDE004V21	315 MHz
745Li	2005-2005		RDE002V21	433 MHz
750i	2014	UVS4010/UVS4011	RDE012V21	433 MHz
750i	2006-2010	UVS2000	RDE008V21	433 MHz
750i	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
750i	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
750iL	1997-2001		RDE004V21	315 MHz
750iL	1998-2001		RDE004V21	315 MHz
750Li	2014	UVS4010/UVS4011	RDE012V21	433 MHz
750Li	2006-2010	UVS2000	RDE008V21	433 MHz
750Li	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
750Li	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
760i	2006	UVS2000	RDE008V21	433 MHz
760i	2004-2005		RDE002V21	433 MHz
760Li	2014	UVS4010/UVS4011	RDE012V21	433 MHz
760Li	2003-2005		RDE002V21	433 MHz
760Li	2006-2010	UVS2000	RDE008V21	433 MHz
760Li	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
760Li	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
ActiveHybrid 3	2013-2014	UVS4010/UVS4011	RDE017V21	433 MHz
ActiveHybrid 3	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
ActiveHybrid 5	2014	UVS4010/UVS4011	RDE017V21	433 MHz
ActiveHybrid 5	2013-2014	UVS4010/UVS4011	RDE012V21	433 MHz
ActiveHybrid 7	2014	UVS4010/UVS4011	RDE017V21	433 MHz
ActiveHybrid 7	2013-2014	UVS4010/UVS4011	RDE012V21	433 MHz
Alpina B6 xDrive Gran Coupe	2015	UVS4010/UVS4011	RDE017V21	433 MHz
Alpina B7	2011		RDE002V21	433 MHz
Alpina B7	2014	UVS4010/UVS4011	RDE017V21	433 MHz
Alpina B7	2007-2008	UVS2000	RDE008V21	433 MHz
Alpina B7	2012-2014	UVS4010/UVS4011	RDE012V21	433 MHz
i3	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
i8	2015	UVS4010/UVS4011	RDE027V21	433 MHz
M235i	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
M3	2001		RDE004V21	315 MHz
M3	2015	UVS4010/UVS4011	RDE027V21	433 MHz
M3	2002-2003		RDE002V21	433 MHz
M3	2004-2009	UVS2000	RDE008V21	433 MHz
M3	2009-2013	UVS4010/UVS4011	RDE012V21	433 MHz
M4	2015	UVS4010/UVS4011	RDE027V21	433 MHz
M5	2014		RDE012V21	433 MHz
M5	2000-2003		RDE004V21	315 MHz
M5	2000-2003	UVS4010/UVS4011	RDE002V21	433 MHz
M5	2006-2010	UVS2000	RDE008V21	433 MHz
M5	2010-2013		RDE012V21	433 MHz
M5	2014-2015		RDE017V21	433 MHz
M6	2006-2010	UVS2000	RDE008V21	433 MHz
M6	2012-2014	UVS4010/UVS4011	RDE012V21	433 MHz
M6	2014-2016	UVS4010/UVS4011	RDE017V21	433 MHz
X1	2013-2014	UVS4010/UVS4011	RDE012V21	433 MHz
X1	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
X3	2006-2010	UVS2000	RDE008V21	433 MHz
X3	2010-2014	UVS4010/UVS4011	RDE012V21	433 MHz
X3	2014-2016	UVS4010/UVS4011	RDE017V21	433 MHz
X4	2015-2016	UVS4010/UVS4011	RDE017V21	433 MHz
X5	2000-2004		RDE003V21	433 MHz
X5	2005-2010	UVS2000	RDE008V21	433 MHz
X5	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
X5	2013-2015	UVS4010/UVS4011	RDE027V21	433 MHz
X6	2011		RDE022V21	315 MHz
X6	2008-2010	UVS2000	RDE008V21	433 MHz
X6	2010-2014	UVS4010/UVS4011	RDE012V21	433 MHz
X6	2014-2015	UVS4010/UVS4011	RDE027V21	433 MHz
Z3	2000-2002		RDE004V21	315 MHz
Z4	2014	UVS4010/UVS4011	RDE012V21	433 MHz
Z4	2003-2010	UVS2000	RDE008V21	433 MHz
Z4	2010-2013	UVS4010/UVS4011	RDE012V21	433 MHz
Z4	2014-2016	UVS4010/UVS4011	RDE017V21	433 MHz
Buick				
Allure	2007-2010	UVS3010/UVS3011		315 MHz
Enclave	2015	UVS3010/UVS3011		315 MHz
Enclave	2008-2014	UVS3010/UVS3011		315 MHz
Encore	2013-2015	UVS3010/UVS3011		315 MHz
LaCrosse	2006-2015	UVS3010/UVS3011		315 MHz
Lucerne	2007-2011	UVS3010/UVS3011		315 MHz
Rainier	2006-2007	UVS3010/UVS3011		315 MHz
Regal	2011-2015	UVS3010/UVS3011		315 MHz
Verano	2012-2015	UVS3010/UVS3011		315 MHz
Cadillac				

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
ATS	2013-2015	UVS3010/UVS3011		315 MHz
CTS	2004-2015	UVS3010/UVS3011		315 MHz
CTS	2014-2015	UVS3010/UVS3011		315 MHz
DTS	2006-2011	UVS3010/UVS3011		315 MHz
ELR	2014-2015	UVS3010/UVS3011		315 MHz
Escalade	2004-2015	UVS3010/UVS3011		315 MHz
Escalade ESV	2015	UVS3010/UVS3011		315 MHz
SRX	2004-2015	UVS3010/UVS3011		315 MHz
SRX	2007-2009	UVS4010/UVS4011		433 MHz
STS	2009	UVS4010/UVS4011		433 MHz
STS	2005-2011	UVS3010/UVS3011		315 MHz
XLR	2004-2009	UVS3010/UVS3011		315 MHz
XTS	2013-2015	UVS3010/UVS3011		315 MHz
Chevrolet				
Avalanche	2004	UVS3010/UVS3011		315 MHz
Avalanche	2005-2013	UVS3010/UVS3011		315 MHz
Camaro	2010-2015	UVS3010/UVS3011		315 MHz
Camaro	2012-2015	UVS3010/UVS3011		315 MHz
Caprice	2011-2015	UVS3010/UVS3011		315 MHz
Captiva Sport	2012-2015	UVS3010/UVS3011		315 MHz
City Express	2015	UVS3010/UVS3011		315 MHz
Cobalt	2008-2010	UVS3010/UVS3011		315 MHz
Colorado	2015	UVS3010/UVS3011		315 MHz
Colorado	2007-2012	UVS3010/UVS3011		315 MHz
Corvette	2005-2014	UVS3010/UVS3011		315 MHz
Corvette	2014-2015	UVS4010/UVS4011		433 MHz
Cruze	2011-2016	UVS3010/UVS3011		315 MHz
Equinox	2007-2015	UVS3010/UVS3011		315 MHz
Express 1500	2008-2014	UVS3010/UVS3011		315 MHz
Express 2500	2008-2015	UVS3010/UVS3011		315 MHz
Express 3500	2008-2015	UVS3010/UVS3011		315 MHz
HHR	2008-2011	UVS3010/UVS3011		315 MHz
Impala	2006-2015	UVS3010/UVS3011		315 MHz
Impala Limited	2014	UVS3010/UVS3011		315 MHz
Malibu	2008-2015	UVS3010/UVS3011		315 MHz
Monte Carlo	2006-2007	UVS3010/UVS3011		315 MHz
Oriando	2012-2015	UVS3010/UVS3011		315 MHz
Silverado 1500	2004	UVS3010/UVS3011		315 MHz
Silverado 1500	2005-2015	UVS3010/UVS3011		315 MHz
Silverado 2500 HD	2004	UVS3010/UVS3011		315 MHz
Silverado 2500 HD	2005-2015	UVS3010/UVS3011		315 MHz
Silverado 3500 HD	2004	UVS3010/UVS3011		315 MHz
Silverado 3500 HD	2005-2015	UVS3010/UVS3011		315 MHz
Sonic	2012-2014	UVS3010/UVS3011		315 MHz
Spark	2013-2015	UVS3010/UVS3011		315 MHz
SS	2014-2015	UVS3010/UVS3011		315 MHz
SSR	2006	UVS3010/UVS3011		315 MHz
Suburban	2015	UVS3010/UVS3011		315 MHz
Suburban 1500	2004	UVS3010/UVS3011		315 MHz
Suburban 1500	2005-2014	UVS3010/UVS3011		315 MHz
Suburban 2500	2004	UVS3010/UVS3011		315 MHz
Suburban 2500	2005-2013	UVS3010/UVS3011		315 MHz
Tahoe	2004	UVS3010/UVS3011		315 MHz
Tahoe	2005-2015	UVS3010/UVS3011		315 MHz
Trailblazer	2006-2009	UVS3010/UVS3011		315 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Traverse	2015	UVS3010/UVS3011		315 MHz
Traverse	2009-2014	UVS3010/UVS3011		315 MHz
Trax	2013-2015	UVS3010/UVS3011		315 MHz
Uplander	2008	UVS3010/UVS3011		315 MHz
Volt	2011-2015	UVS3010/UVS3011		315 MHz
Chrysler				
200	2011-2014	UVS3010/UVS3011		315 MHz
300	2005-2007	UVS3010/UVS3011		315 MHz
300	2006-2015	UVS4010/UVS4011		433 MHz
300M	2002-2004	UVS4010/UVS4011		433 MHz
Aspen	2007-2009	UVS3010/UVS3011		315 MHz
Concorde	2002-2004	UVS4010/UVS4011		433 MHz
Crossfire	2004-2008	UVS4010/UVS4011		433 MHz
Crossfire	2006-2008	UVS3010/UVS3011		315 MHz
Pacifica	2004	UVS3010/UVS3011		315 MHz
Pacifica	2004	UVS4010/UVS4011		433 MHz
Pacifica	2005-2008	UVS3010/UVS3011		315 MHz
Prowler	2002	UVS4010/UVS4011		433 MHz
PT Cruiser	2008-2010	UVS3010/UVS3011		315 MHz
Sebring	2007-2010	UVS3010/UVS3011		315 MHz
Sebring	2008	UVS4010/UVS4011		433 MHz
Sebring	2009	UVS4010/UVS4011		433 MHz
Town & Country	2002-2003	UVS4010/UVS4011		433 MHz
Town & Country	2004-2007	UVS3010/UVS3011		315 MHz
Town & Country	2008-2015	UVS4010/UVS4011		433 MHz
Voyager	2002-2003	UVS4010/UVS4011		433 MHz
Dodge				
Avenger	2008-2014	UVS3010/UVS3011		315 MHz
Caliber	2007-2012	UVS3010/UVS3011		315 MHz
Caravan	2002-2003	UVS4010/UVS4011		433 MHz
Caravan	2004-2007	UVS3010/UVS3011		315 MHz
Challenger	2008-2015	UVS4010/UVS4011		433 MHz
Charger	2006-2007	UVS3010/UVS3011		315 MHz
Charger	2008-2015	UVS4010/UVS4011		433 MHz
Dakota	2011	UVS3010/UVS3011		315 MHz
Dakota	2008-2010	UVS3010/UVS3011		315 MHz
Dakota	2008-2010	UVS3010/UVS3011		315 MHz
Durango	2007-2009	UVS3010/UVS3011		315 MHz
Durango	2011-2015	UVS4010/UVS4011		433 MHz
Grand Caravan	2002-2003	UVS4010/UVS4011		433 MHz
Grand Caravan	2004-2007	UVS3010/UVS3011		315 MHz
Grand Caravan	2008-2015	UVS4010/UVS4011		433 MHz
Intrepid	2002-2004	UVS4010/UVS4011		433 MHz
Journey	2009-2015	UVS4010/UVS4011		433 MHz
Magnum	2008	UVS4010/UVS4011		433 MHz
Magnum	2005-2007	UVS3010/UVS3011		315 MHz
Nitro	2007-2011	UVS3010/UVS3011		315 MHz
Ram 1500	2008	UVS3010/UVS3011		315 MHz
Ram 1500	2009	UVS4010/UVS4011		433 MHz
Ram 1500	2009	UVS3010/UVS3011		315 MHz
Ram 1500	2010	UVS4010/UVS4011		433 MHz
Ram 2500	2008-2009	UVS3010/UVS3011		315 MHz
Ram 2500	2009-2010	UVS4010/UVS4011		433 MHz
Ram 3500	2008-2009	UVS3010/UVS3011		315 MHz
Ram 3500	2009-2010	UVS4010/UVS4011		433 MHz
Sprinter 2500	2007-2009	UVS3010/UVS3011		315 MHz

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Sprinter 3500	2007-2009	UVS3010/UVS3011		315 MHz
Stratus	2007	UVS3010/UVS3011		315 MHz
Viper	2003-2006	UVS4010/UVS4011		433 MHz
Viper	2008-2010	UVS4010/UVS4011		433 MHz
Ferrari				
458 Italia	2009-2013	UVS2000	RDE011V21	433 MHz
550 Maranello	2001		RDE001V21	433 MHz
575 M Maranello	2002-2005		RDE004V21	315 MHz
575 M Maranello	2002-2006		RDE001V21	433 MHz
599 GTB	2006-2012		RDE001V21	433 MHz
612 Scaglietti	2004-2011		RDE001V21	433 MHz
California	2009-2014	UVS2000	RDE011V21	433 MHz
Enzo	2003-2004		RDE005V21	433 MHz
F12 Berlinetta	2012-2014	UVS2000	RDE011V21	433 MHz
F430	2005-2007		RDE001V21	433 MHz
F430	2007-2009	UVS2000	RDE011V21	433 MHz
FF	2012-2014	UVS2000	RDE011V21	433 MHz
Fiat				
500	2012-2015	UVS4010/UVS4011		433 MHz
500L	2014-2015	UVS4010/UVS4011		433 MHz
Ford				
C-Max	2013-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Crown Victoria	2006-2011	UVS3010/UVS3011	RDE014V21	315 MHz
E-150	2010	UVS3010/UVS3011	RDE015V21	315 MHz
E-150	2010	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
E-150	2007-2009	UVS3010/UVS3011	RDE015V21	315 MHz
E-150	2011-2014	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
E-250	2010	UVS3010/UVS3011	RDE015V21	315 MHz
E-250	2010	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
E-250	2007-2009	UVS3010/UVS3011	RDE015V21	315 MHz
E-250	2011-2014	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
E-350 Super Duty	2010	UVS3010/UVS3011	RDE015V21	315 MHz
E-350 Super Duty	2010	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
E-350 Super Duty	2007-2009		RDE015V21	315 MHz
E-350 Super Duty	2011-2014	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
E-450 Super Duty	2010	UVS3010/UVS3011	RDE015V21	315 MHz
E-450 Super Duty	2010	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
E-450 Super Duty	2007-2009	UVS3010/UVS3011	RDE015V21	315 MHz
E-450 Super Duty	2011-2014	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Edge	2007-2010	UVS3010/UVS3011	RDE014V21	315 MHz
Edge	2011-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Escape	2005-2008	UVS3010/UVS3011	RDE014V21	315 MHz
Escape	2009-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Expedition	2005-2006	UVS3010/UVS3011		315 MHz
Expedition	2007-2010	UVS3010/UVS3011	RDE014V21	315 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Expedition	2011-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Explorer	2016	UVS3010/UVS3011		315 MHz
Explorer	2006-2010	UVS3010/UVS3011	RDE014V21	315 MHz
Explorer	2011-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Explorer Sport Trac	2007-2010	UVS3010/UVS3011	RDE014V21	315 MHz
F-150	2006-2008	UVS3010/UVS3011	RDE015V21	315 MHz
F-150	2006-2008	UVS3010/UVS3011	RDE014V21	315 MHz
F-150	2009-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
F-250 Super Duty	2008-2010	UVS3010/UVS3011	RDE015V21	315 MHz
F-250 Super Duty	2010-2016	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
F-350 Super Duty	2008-2010	UVS3010/UVS3011	RDE015V21	315 MHz
F-350 Super Duty	2010-2016	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
F-450 Super Duty	2008-2010	UVS3010/UVS3011	RDE015V21	315 MHz
F-450 Super Duty	2010-2016	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Fiesta	2011-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Five Hundred	2006-2007	UVS3010/UVS3011	RDE014V21	315 MHz
Flex	2009-2010	UVS3010/UVS3011	RDE014V21	315 MHz
Flex	2011-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Focus	2007-2009	UVS3010/UVS3011	RDE014V21	315 MHz
Focus	2010-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Freestar	2004-2005	UVS3010/UVS3011		315 MHz
Freestar	2006-2007	UVS3010/UVS3011	RDE014V21	315 MHz
Fusion	2007-2009	UVS3010/UVS3011	RDE014V21	315 MHz
Fusion	2010-2016	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Mustang	2006-2009	UVS3010/UVS3011	RDE014V21	315 MHz
Mustang	2010-2012	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Mustang	2013-2014	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Mustang	2013-2014	UVS3010/UVS3011		315 MHz
Mustang	2015	UVS3010/UVS3011		315 MHz
Ranger	2007-2011	UVS3010/UVS3011	RDE014V21	315 MHz
Taurus	2008-2010	UVS3010/UVS3011	RDE014V21	315 MHz
Taurus	2010-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Taurus	2010-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Taurus X	2008	UVS3010/UVS3011	RDE014V21	315 MHz
Transit Connect	2010-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Transit Connect	2010-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Transit-150	2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Transit-150	2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Transit-250	2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Transit-250	2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Transit-350	2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Transit-350	2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Freightliner				
Sprinter 2500	2014	UVS4010/UVS4011		433 MHz
Sprinter 2500	2007-2013	UVS3010/UVS3011		315 MHz
Sprinter 3500	2014	UVS4010/UVS4011		433 MHz
Sprinter 3500	2007-2013	UVS3010/UVS3011		315 MHz
GMC				
Acadia	2015	UVS3010/UVS3011		315 MHz
Acadia	2007-2014	UVS3010/UVS3011		315 MHz
Canyon	2015	UVS3010/UVS3011		315 MHz
Canyon	2007-2012	UVS3010/UVS3011		315 MHz
Envoy	2005-2009	UVS3010/UVS3011		315 MHz
Savana 1500	2008-2014	UVS3010/UVS3011		315 MHz
Savana 2500	2008-2015	UVS3010/UVS3011		315 MHz
Savana 3500	2008-2015	UVS3010/UVS3011		315 MHz
Sierra 1500	2004	UVS3010/UVS3011		315 MHz
Sierra 1500	2005-2015	UVS3010/UVS3011		315 MHz
Sierra 2500 HD	2004	UVS3010/UVS3011		315 MHz
Sierra 2500 HD	2005-2015	UVS3010/UVS3011		315 MHz
Sierra 3500 HD	2004	UVS3010/UVS3011		315 MHz
Sierra 3500 HD	2005-2015	UVS3010/UVS3011		315 MHz
Terrain	2010-2015	UVS3010/UVS3011		315 MHz
Yukon	2004	UVS3010/UVS3011		315 MHz
Yukon	2005-2015	UVS3010/UVS3011		315 MHz
Yukon XL	2015	UVS3010/UVS3011		315 MHz
Yukon XL 1500	2004	UVS3010/UVS3011		315 MHz
Yukon XL 1500	2005-2012	UVS3010/UVS3011		315 MHz
Yukon XL 2500	2004	UVS3010/UVS3011		315 MHz
Yukon XL 2500	2005-2011	UVS3010/UVS3011		315 MHz
Honda				
Accord	2008-2012	UVS3010/UVS3011		315 MHz
Accord Cross-tour	2010-2012	UVS3010/UVS3011		315 MHz
Civic	2008-2013	UVS3010/UVS3011		315 MHz
Crosstour	2013-2015	UVS3010/UVS3011		315 MHz
CR-V	2007-2013	UVS3010/UVS3011		315 MHz
CR-Z	2011-2015	UVS3010/UVS3011		315 MHz
Element	2009-2011	UVS3010/UVS3011		315 MHz
Fit	2008-2014	UVS3010/UVS3011		315 MHz
Insight	2010-2014	UVS3010/UVS3011		315 MHz
Odyssey	2011-2015	UVS3010/UVS3011		315 MHz
S2000	2008-2009	UVS3010/UVS3011		315 MHz
Hummer				
H2	2008-2010	UVS3010/UVS3011		315 MHz
H3	2006-2010	UVS3010/UVS3011		315 MHz
H3T	2009-2010	UVS3010/UVS3011		315 MHz
Hyundai				
Accent	2015	UVS4010/UVS4011		433 MHz
Accent	2006-2014	UVS3010/UVS3011		315 MHz
Azera	2013	UVS3010/UVS3011		315 MHz
Azera	2006-2012	UVS3010/UVS3011	RDE019V21	315 MHz
Elantra	2010	UVS3010/UVS3011	RDE019V21	315 MHz
Elantra	2009-2012	UVS3010/UVS3011		315 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Elantra	2011-2016	UVS3010/UVS3011		315 MHz
Elantra GT	2013-2015	UVS3010/UVS3011		315 MHz
Entourage	2007-2010	UVS3010/UVS3011	RDE020V21	315 MHz
Genesis Coupe	2010-2015	UVS3010/UVS3011		315 MHz
Santa Fe	2007-2008	UVS3010/UVS3011	RDE020V21	315 MHz
Santa Fe	2009-2010	UVS3010/UVS3011	RDE019V21	315 MHz
Santa Fe	2010-2012	UVS3010/UVS3011		315 MHz
Santa Fe	2013-2016	UVS3010/UVS3011		315 MHz
Sonata	2015	UVS3010/UVS3011		315 MHz
Sonata	2007-2010	UVS3010/UVS3011		315 MHz
Sonata	2011-2014	UVS3010/UVS3011		315 MHz
Tiburon	2007-2008	UVS3010/UVS3011		315 MHz
Tucson	2006-2013	UVS3010/UVS3011		315 MHz
Veloster	2012-2015	UVS3010/UVS3011		315 MHz
Veracruz	2007-2008	UVS3010/UVS3011	RDE020V21	315 MHz
Veracruz	2008-2012	UVS3010/UVS3011	RDE019V21	315 MHz
Infiniti				
EX35	2008-2012	UVS3010/UVS3011		315 MHz
EX37	2013	UVS3010/UVS3011		315 MHz
FX35	2003-2012	UVS3010/UVS3011		315 MHz
FX37	2013	UVS3010/UVS3011		315 MHz
FX45	2003-2008	UVS3010/UVS3011		315 MHz
FX50	2009-2013	UVS3010/UVS3011		315 MHz
G25	2011-2012	UVS3010/UVS3011		315 MHz
G35	2003-2008	UVS3010/UVS3011		315 MHz
G37	2008-2013	UVS3010/UVS3011		315 MHz
JX35	2013	UVS4010/UVS4011		433 MHz
M35	2006-2010	UVS3010/UVS3011		315 MHz
M35h	2012-2013	UVS3010/UVS3011		315 MHz
M37	2011-2013	UVS3010/UVS3011		315 MHz
M45	2003-2011	UVS3010/UVS3011		315 MHz
M56	2011-2013	UVS3010/UVS3011		315 MHz
Q40	2015	UVS3010/UVS3011		315 MHz
Q45	2003-2006	UVS3010/UVS3011		315 MHz
Q50	2014-2015	UVS3010/UVS3011		315 MHz
Q60	2014-2015	UVS3010/UVS3011		315 MHz
Q70	2014-2015	UVS3010/UVS3011		315 MHz
QX4	2003	UVS3010/UVS3011		315 MHz
QX50	2014-2015	UVS3010/UVS3011		315 MHz
QX56	2004-2013	UVS3010/UVS3011		315 MHz
QX60	2014	UVS4010/UVS4011		433 MHz
QX70	2014-2016	UVS3010/UVS3011		315 MHz
QX80	2014-2015	UVS3010/UVS3011		315 MHz
Isuzu				
Ascender	2006-2008	UVS3010/UVS3011		315 MHz
i-290	2007-2009	UVS3010/UVS3011		315 MHz
i-370	2007-2009	UVS3010/UVS3011		315 MHz
Rodeo	2004	UVS4010/UVS4011		433 MHz
Jaguar				
F-Type	2014-2016	UVS3010/UVS3011		315 MHz
S-Type	2005-2008	UVS3010/UVS3011		315 MHz
Super V8	2005-2009	UVS3010/UVS3011		315 MHz
Vanden Plas	2004-2009	UVS3010/UVS3011		315 MHz
XF	2009-2015	UVS3010/UVS3011		315 MHz
XFR	2010-2012	UVS3010/UVS3011		315 MHz
XJ	2011	UVS3010/UVS3011		315 MHz
XJ	2012-2015	UVS3010/UVS3011		315 MHz
XJ8	2004-2009	UVS3010/UVS3011		315 MHz
XJR	2004-2009	UVS3010/UVS3011		315 MHz

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
XK	2007-2012	UVS3010/UVS3011		315 MHz
XK	2013-2015	UVS3010/UVS3011		315 MHz
XK8	2005-2006	UVS3010/UVS3011		315 MHz
XKR	2013	UVS3010/UVS3011		315 MHz
XKR	2005-2012	UVS3010/UVS3011		315 MHz
X-Type	2008	UVS3010/UVS3011		315 MHz
Jeep				
Cherokee	2014-2015	UVS4010/UVS4011		433 MHz
Commander	2006-2007	UVS3010/UVS3011		315 MHz
Commander	2008-2010	UVS4010/UVS4011		433 MHz
Compass	2007-2013	UVS3010/UVS3011		315 MHz
Compass	2014-2015	UVS3010/UVS3011		315 MHz
Grand Cherokee	2002-2004	UVS4010/UVS4011		433 MHz
Grand Cherokee	2005-2007	UVS3010/UVS3011		315 MHz
Grand Cherokee	2008-2015	UVS4010/UVS4011		433 MHz
Liberty	2004	UVS4010/UVS4011		433 MHz
Liberty	2009	UVS4010/UVS4011		433 MHz
Liberty	2005-2012	UVS3010/UVS3011		315 MHz
Patriot	2007-2013	UVS3010/UVS3011		315 MHz
Patriot	2014-2015	UVS3010/UVS3011		315 MHz
Wrangler	2007-2008	UVS3010/UVS3011		315 MHz
Wrangler	2009-2010	UVS4010/UVS4011		433 MHz
Wrangler	2009-2012	UVS3010/UVS3011		315 MHz
Wrangler	2013-2015	UVS4010/UVS4011		433 MHz
Kia				
Amanti	2007-2009	UVS3010/UVS3011		315 MHz
Borrego	2009-2011	UVS3010/UVS3011		315 MHz
Cadenza	2014	UVS4010/UVS4011		433 MHz
Cadenza	2014-2015	UVS3010/UVS3011		315 MHz
Forte	2010-2013	UVS3010/UVS3011		315 MHz
Magentis	2008-2010	UVS3010/UVS3011	RDE019V21	315 MHz
Optima	2006-2010	UVS3010/UVS3011	RDE019V21	315 MHz
Optima	2011-2013	UVS3010/UVS3011		315 MHz
Optima	2014-2015	UVS3010/UVS3011		315 MHz
Rio	2007-2015	UVS3010/UVS3011		315 MHz
Rio5	2007-2015	UVS3010/UVS3011		315 MHz
Rondo	2006-2010	UVS3010/UVS3011	RDE019V21	315 MHz
Sedona	2006-2008	UVS3010/UVS3011	RDE020V21	315 MHz
Sedona	2009-2015	UVS3010/UVS3011	RDE019V21	315 MHz
Sorento	2014	UVS4010/UVS4011		433 MHz
Sorento	2015	UVS3010/UVS3011		315 MHz
Sorento	2016	UVS4010/UVS4011		433 MHz
Sorento	2005-2009	UVS3010/UVS3011		315 MHz
Sorento	2011-2014	UVS3010/UVS3011		315 MHz
Soul	2010-2013	UVS3010/UVS3011		315 MHz
Soul	2014-2015	UVS4010/UVS4011		433 MHz
Spectra	2006-2009	UVS3010/UVS3011		315 MHz
Spectra5	2007-2009	UVS3010/UVS3011		315 MHz
Sportage	2005-2013	UVS3010/UVS3011		315 MHz
Lamborghini				
Aventador	2011-2015	UVS2000	RDE011V21	433 MHz
Gallardo	2007-2014	UVS2000	RDE011V21	433 MHz
Huracan	2015	UVS2000	RDE011V21	433 MHz
Murcielago	2007-2011	UVS2000	RDE011V21	433 MHz
Land Rover				
LR2	2008-2015	UVS3010/UVS3011		315 MHz
LR3	2005		RDE003V21	433 MHz
LR3	2006-2009	UVS3010/UVS3011		315 MHz
LR4	2010-2013	UVS3010/UVS3011		315 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Range Rover	2002-2005		RDE003V21	433 MHz
Range Rover	2006-2011	UVS3010/UVS3011		315 MHz
Range Rover	2012-2014	UVS3010/UVS3011		315 MHz
Range Rover Evoque	2012-2015	UVS3010/UVS3011		315 MHz
Range Rover Sport	2006-2011	UVS3010/UVS3011		315 MHz
Range Rover Sport	2012-2014	UVS3010/UVS3011		315 MHz
Lexus				
CT200h	2011-2015	UVS3010/UVS3011		315 MHz
ES300h	2013-2015	UVS3010/UVS3011		315 MHz
ES350	2007-2015	UVS3010/UVS3011		315 MHz
GS300	2005-2006	UVS3010/UVS3011		315 MHz
GS350	2007-2015	UVS3010/UVS3011		315 MHz
GS430	2005-2007	UVS3010/UVS3011		315 MHz
GS450h	2007-2015	UVS3010/UVS3011		315 MHz
GS460	2008-2012	UVS3010/UVS3011		315 MHz
GX460	2010-2015	UVS3010/UVS3011		315 MHz
GX470	2004-2009	UVS3010/UVS3011		315 MHz
HS250h	2010-2012	UVS3010/UVS3011		315 MHz
IS F	2008-2015	UVS3010/UVS3011		315 MHz
IS250	2006-2015	UVS3010/UVS3011		315 MHz
IS350	2006-2015	UVS3010/UVS3011		315 MHz
LFA	2012-2015	UVS3010/UVS3011		315 MHz
LS460	2007-2015	UVS3010/UVS3011		315 MHz
LS600h	2008-2014	UVS3010/UVS3011		315 MHz
LX470	2005-2007	UVS3010/UVS3011		315 MHz
LX570	2008-2015	UVS3010/UVS3011		315 MHz
NX200t	2015	UVS3010/UVS3011		315 MHz
NX300h	2015	UVS3010/UVS3011		315 MHz
RC F	2015	UVS3010/UVS3011		315 MHz
RC350	2015	UVS3010/UVS3011		315 MHz
RX330	2006	UVS3010/UVS3011		315 MHz
RX350	2007-2015	UVS3010/UVS3011		315 MHz
RX400h	2006-2009	UVS3010/UVS3011		315 MHz
RX450h	2010-2015	UVS3010/UVS3011		315 MHz
SC430	2006-2010	UVS3010/UVS3011		315 MHz
Lincoln				
Mark LT	2007-2008	UVS3010/UVS3011	RDE015V21	315 MHz
Mark LT	2007-2008	UVS3010/UVS3011	RDE014V21	315 MHz
MKC	2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
MKS	2009-2010	UVS3010/UVS3011	RDE014V21	315 MHz
MKS	2011-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
MKT	2010	UVS3010/UVS3011	RDE014V21	315 MHz
MKT	2011-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
MKX	2007-2010	UVS3010/UVS3011	RDE014V21	315 MHz
MKX	2011-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
MKZ	2007-2009	UVS3010/UVS3011	RDE014V21	315 MHz
MKZ	2010-2016	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Navigator	2005-2006	UVS3010/UVS3011		315 MHz
Navigator	2007-2010	UVS3010/UVS3011	RDE014V21	315 MHz
Navigator	2011-2015	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Town Car	2006-2011	UVS3010/UVS3011	RDE014V21	315 MHz

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Zephyr	2006	UVS3010/UVS3011	RDE014V21	315 MHz
Lotus				
Elise	2008-2011	UVS4010/UVS4011		433 MHz
Evora	2010-2014	UVS4010/UVS4011		433 MHz
Exige	2008-2010	UVS4010/UVS4011		433 MHz
Maserati				
Coupe	2004-2009		RDE001V21	433 MHz
Coupe	2009-2011	UVS2000	RDE011V21	433 MHz
GranCabrio	2010-2013	UVS2000	RDE011V21	433 MHz
GranSport	2005	UVS2000	RDE011V21	433 MHz
GranTurismo	2008-2013	UVS2000	RDE011V21	433 MHz
Quattroporte	2004-2009		RDE001V21	433 MHz
Quattroporte	2010-2013	UVS2000	RDE011V21	433 MHz
Spyder	2002-2005	UVS2000	RDE011V21	433 MHz
Maybach				
57	2003-2011		RDE001V21	433 MHz
57	2003-2011		RDE004V21	315 MHz
62	2003-2011		RDE001V21	433 MHz
62	2003-2011		RDE004V21	315 MHz
Mazda				
2	2011-2012	UVS3010/UVS3011		315 MHz
2	2012-2014	UVS3010/UVS3011		315 MHz
3	2004-2012	UVS3010/UVS3011		315 MHz
3	2012-2013	UVS3010/UVS3011		315 MHz
5	2006-2015	UVS3010/UVS3011		315 MHz
6	2005-2013	UVS3010/UVS3011		315 MHz
6	2005-2013	UVS3010/UVS3011		315 MHz
B2300	2007-2009	UVS3010/UVS3011	RDE014V21	315 MHz
B3000	2007-2008	UVS3010/UVS3011	RDE014V21	315 MHz
B4000	2007-2009	UVS3010/UVS3011	RDE014V21	315 MHz
CX-7	2007-2012	UVS3010/UVS3011		315 MHz
CX-9	2007-2015	UVS3010/UVS3011		315 MHz
MX-5 Miata	2006-2008	UVS3010/UVS3011		315 MHz
MX-5 Miata	2009-2014	UVS3010/UVS3011		315 MHz
MX-5 Miata	2015	UVS3010/UVS3011		315 MHz
RX-8	2004-2011	UVS3010/UVS3011		315 MHz
Tribute	2006	UVS3010/UVS3011	RDE014V21	315 MHz
Tribute	2011	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Tribute	2011	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Tribute	2008-2010	UVS3010/UVS3011	RDE014V21	315 MHz
Mercedes-Benz				
B Electric Drive	2014	UVS4010/UVS4011		433 MHz
C250	2012-2014	UVS4010/UVS4011		433 MHz
C250	2014-2015	UVS4010/UVS4011		433 MHz
C300	2008-2014	UVS4010/UVS4011		433 MHz
C300	2014-2015	UVS4010/UVS4011		433 MHz
C350	2007-2014	UVS4010/UVS4011		433 MHz
C350	2014-2015	UVS4010/UVS4011		433 MHz
C400	2015	UVS4010/UVS4011		433 MHz
C63 AMG	2008-2014	UVS4010/UVS4011		433 MHz
C63 AMG	2014-2015	UVS4010/UVS4011		433 MHz
CL500	2000-2006		RDE004V21	315 MHz
CL55 AMG	2001-2006		RDE004V21	315 MHz
CL550	2014	UVS4010/UVS4011		433 MHz
CL550	2007-2009	UVS3010/UVS3011	RDE004V21	315 MHz
CL550	2010-2014	UVS4010/UVS4011		433 MHz
CL600	2014	UVS4010/UVS4011		433 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
CL600	2001-2009	UVS3010/UVS3011	RDE004V21	315 MHz
CL600	2010-2014	UVS4010/UVS4011		433 MHz
CL63 AMG	2014	UVS4010/UVS4011		433 MHz
CL63 AMG	2008-2009	UVS3010/UVS3011	RDE004V21	315 MHz
CL63 AMG	2010-2014	UVS4010/UVS4011		433 MHz
CL65 AMG	2014	UVS4010/UVS4011		433 MHz
CL65 AMG	2005-2009	UVS3010/UVS3011	RDE004V21	315 MHz
CL65 AMG	2010-2014	UVS4010/UVS4011		433 MHz
CLA250	2014	UVS4010/UVS4011		433 MHz
CLA250	2014-2015	UVS4010/UVS4011		433 MHz
CLA45 AMG	2014	UVS4010/UVS4011		433 MHz
CLA45 AMG	2014-2015	UVS4010/UVS4011		433 MHz
CLK350	2006-2007		RDE004V21	315 MHz
CLK350	2006-2009	UVS4010/UVS4011		433 MHz
CLK500	2006	UVS4010/UVS4011		433 MHz
CLK55 AMG	2006	UVS4010/UVS4011		433 MHz
CLK550	2007-2009	UVS4010/UVS4011		433 MHz
CLK63 AMG	2007-2009	UVS4010/UVS4011		433 MHz
CLS400	2015	UVS4010/UVS4011		433 MHz
CLS500	2006	UVS3010/UVS3011	RDE004V21	315 MHz
CLS55 AMG	2006	UVS3010/UVS3011	RDE004V21	315 MHz
CLS550	2007-2011	UVS3010/UVS3011	RDE004V21	315 MHz
CLS550	2012-2014	UVS4010/UVS4011		433 MHz
CLS550	2014-2015	UVS4010/UVS4011		433 MHz
CLS63 AMG	2007-2011	UVS3010/UVS3011	RDE004V21	315 MHz
CLS63 AMG	2012-2014	UVS4010/UVS4011		433 MHz
CLS63 AMG	2014-2015	UVS4010/UVS4011		433 MHz
E250	2014	UVS4010/UVS4011		433 MHz
E250	2014-2016	UVS4010/UVS4011		433 MHz
E320	2000-2006		RDE004V21	315 MHz
E320	2006-2009	UVS3010/UVS3011	RDE004V21	315 MHz
E350	2006-2009	UVS3010/UVS3011	RDE004V21	315 MHz
E350	2010-2014	UVS4010/UVS4011		433 MHz
E350	2014-2016	UVS4010/UVS4011		433 MHz
E400	2014	UVS4010/UVS4011		433 MHz
E400	2014-2016	UVS4010/UVS4011		433 MHz
E430	2000		RDE001V21	433 MHz
E430	2000-2002		RDE004V21	315 MHz
E500	2006	UVS3010/UVS3011		315 MHz
E500	2003-2006		RDE004V21	315 MHz
E55 AMG	2006	UVS3010/UVS3011		315 MHz
E55 AMG	1999-2006		RDE004V21	315 MHz
E550	2007-2009	UVS3010/UVS3011	RDE004V21	315 MHz
E550	2010-2014	UVS4010/UVS4011		433 MHz
E550	2014-2016	UVS4010/UVS4011		433 MHz
E63 AMG	2007-2009	UVS3010/UVS3011	RDE004V21	315 MHz
E63 AMG	2010-2014	UVS4010/UVS4011		433 MHz
E63 AMG	2014-2016	UVS4010/UVS4011		433 MHz
G500	2007-2008	UVS4010/UVS4011		433 MHz
G55 AMG	2007-2011	UVS4010/UVS4011		433 MHz
G550	2015	UVS4010/UVS4011		433 MHz
G550	2009-2014	UVS4010/UVS4011		433 MHz
G63 AMG	2015	UVS4010/UVS4011		433 MHz
G63 AMG	2013-2014	UVS4010/UVS4011		433 MHz
GL350	2010-2014	UVS4010/UVS4011		433 MHz
GL350	2014-2015	UVS4010/UVS4011		433 MHz
GL450	2010-2014	UVS4010/UVS4011		433 MHz
GL450	2014-2015	UVS4010/UVS4011		433 MHz
GL550	2010-2014	UVS4010/UVS4011		433 MHz

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
GL63 AMG	2013-2014	UVS4010/UVS4011		433 MHz
GL63 AMG	2014-2015	UVS4010/UVS4011		433 MHz
GLA250	2015	UVS4010/UVS4011		433 MHz
GLA45 AMG	2015	UVS4010/UVS4011		433 MHz
GLK250	2014	UVS4010/UVS4011		433 MHz
GLK250	2014-2015	UVS4010/UVS4011		433 MHz
GLK350	2010-2014	UVS4010/UVS4011		433 MHz
GLK350	2014-2015	UVS4010/UVS4011		433 MHz
ML250	2015	UVS4010/UVS4011		433 MHz
ML350	2010-2014	UVS4010/UVS4011		433 MHz
ML350	2014-2015	UVS4010/UVS4011		433 MHz
ML400	2015	UVS4010/UVS4011		433 MHz
ML450	2010-2011	UVS4010/UVS4011		433 MHz
ML550	2010-2014	UVS4010/UVS4011		433 MHz
ML550	2014	UVS4010/UVS4011		433 MHz
ML63 AMG	2010-2014	UVS4010/UVS4011		433 MHz
ML63 AMG	2014-2015	UVS4010/UVS4011		433 MHz
R350	2012	UVS4010/UVS4011		433 MHz
S350	2006		RDE004V21	315 MHz
S400	2010	UVS3010/UVS3011	RDE004V21	315 MHz
S400	2010-2013	UVS4010/UVS4011		433 MHz
S430	2000-2006		RDE004V21	315 MHz
S450	2009	UVS3010/UVS3011	RDE004V21	315 MHz
S500	2000		RDE001V21	433 MHz
S500	2000-2006		RDE004V21	315 MHz
S55 AMG	2001-2006		RDE004V21	315 MHz
S550	2007-2009	UVS3010/UVS3011	RDE004V21	315 MHz
S550	2010-2014	UVS4010/UVS4011		433 MHz
S550	2014-2015	UVS4010/UVS4011		433 MHz
S600	2001-2007		RDE004V21	315 MHz
S600	2007-2009	UVS3010/UVS3011	RDE004V21	315 MHz
S600	2010-2013	UVS4010/UVS4011		433 MHz
S600	2015-2016	UVS4010/UVS4011		433 MHz
S63 AMG	2008-2009	UVS3010/UVS3011	RDE004V21	315 MHz
S63 AMG	2011-2014	UVS4010/UVS4011		433 MHz
S63 AMG	2014-2015	UVS4010/UVS4011		433 MHz
S65 AMG	2006		RDE004V21	315 MHz
S65 AMG	2007-2009	UVS3010/UVS3011	RDE004V21	315 MHz
S65 AMG	2010-2013	UVS4010/UVS4011		433 MHz
S65 AMG	2015	UVS4010/UVS4011		433 MHz
SL400	2015	UVS4010/UVS4011		433 MHz
SL500	2006	UVS3010/UVS3011		315 MHz
SL500	2000-2006		RDE004V21	315 MHz
SL55 AMG	2003-2008		RDE004V21	315 MHz
SL55 AMG	2006-2008	UVS3010/UVS3011		315 MHz
SL550	2007-2009	UVS3010/UVS3011	RDE004V21	315 MHz
SL550	2011-2012	UVS3010/UVS3011	RDE004V21	315 MHz
SL550	2013-2014	UVS4010/UVS4011		433 MHz
SL550	2014-2015	UVS4010/UVS4011		433 MHz
SL600	2000-2009		RDE004V21	315 MHz
SL600	2006-2009	UVS3010/UVS3011		315 MHz
SL63 AMG	2009	UVS3010/UVS3011	RDE004V21	315 MHz
SL63 AMG	2013	UVS4010/UVS4011		433 MHz
SL63 AMG	2011-2012	UVS3010/UVS3011	RDE004V21	315 MHz
SL63 AMG	2014-2015	UVS4010/UVS4011		433 MHz
SL65 AMG	2011	UVS3010/UVS3011	RDE004V21	315 MHz
SL65 AMG	2005-2009		RDE004V21	315 MHz
SL65 AMG	2006-2009	UVS3010/UVS3011		315 MHz
SL65 AMG	2013-2014	UVS4010/UVS4011		433 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
SL65 AMG	2014-2015	UVS4010/UVS4011		433 MHz
SLK250	2012-2014	UVS4010/UVS4011		433 MHz
SLK250	2014-2015	UVS4010/UVS4011		433 MHz
SLK280	2007-2008	UVS4010/UVS4011		433 MHz
SLK300	2009-2011	UVS4010/UVS4011		433 MHz
SLK350	2007-2014	UVS4010/UVS4011		433 MHz
SLK350	2014-2015	UVS4010/UVS4011		433 MHz
SLK55 AMG	2007-2010	UVS4010/UVS4011		433 MHz
SLK55 AMG	2012-2014	UVS4010/UVS4011		433 MHz
SLK55 AMG	2014-2015	UVS4010/UVS4011		433 MHz
SLR McLaren	2004-2009		RDE001V21	433 MHz
SLR McLaren	2008-2009	UVS3010/UVS3011		315 MHz
SLS AMG	2011-2014	UVS4010/UVS4011		433 MHz
SLS AMG	2014-2015	UVS4010/UVS4011		433 MHz
Sprinter 2500	2010-2013	UVS3010/UVS3011		315 MHz
Sprinter 2500	2014-2015	UVS4010/UVS4011		433 MHz
Sprinter 3500	2010-2013	UVS3010/UVS3011		315 MHz
Sprinter 3500	2014-2015	UVS4010/UVS4011		433 MHz
Mercury				
Grand Marquis	2006-2011	UVS3010/UVS3011	RDE014V21	315 MHz
Mariner	2005-2008	UVS3010/UVS3011	RDE014V21	315 MHz
Mariner	2009-2011	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Milan	2007	UVS3010/UVS3011	RDE014V21	315 MHz
Milan	2007-2009	UVS3010/UVS3011	RDE014V21	315 MHz
Milan	2010-2011	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz
Montego	2006-2007	UVS3010/UVS3011	RDE014V21	315 MHz
Monterey	2004-2005	UVS3010/UVS3011		315 MHz
Monterey	2006-2007	UVS3010/UVS3011	RDE014V21	315 MHz
Mountaineer	2006-2010	UVS3010/UVS3011	RDE014V21	315 MHz
Sable	2008-2009	UVS3010/UVS3011	RDE014V21	315 MHz
Mini				
Cooper	2007-2009	UVS2000	RDE008V21	433 MHz
Cooper	2010-2014	UVS4010/UVS4011	RDE012V21	433 MHz
Cooper	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
Cooper Countryman	2011-2014	UVS4010/UVS4011	RDE012V21	433 MHz
Cooper Countryman	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
Cooper Pace-man	2013-2014	UVS4010/UVS4011	RDE012V21	433 MHz
Cooper Pace-man	2014-2015	UVS4010/UVS4011	RDE017V21	433 MHz
Mitsubishi				
Eclipse	2006-2007	UVS3010/UVS3011		315 MHz
Eclipse	2006-2007	UVS3010/UVS3011		315 MHz
Eclipse	2008-2012	UVS3010/UVS3011		315 MHz
Endeavor	2004-2006	UVS4010/UVS4011		433 MHz
Endeavor	2006-2009	UVS3010/UVS3011		315 MHz
Endeavor	2010-2011	UVS3010/UVS3011		315 MHz
Galant	2004-2006	UVS4010/UVS4011		433 MHz
Galant	2007-2012	UVS3010/UVS3011		315 MHz
i-MiEV	2012-2014	UVS3010/UVS3011		315 MHz
Lancer	2008-2015	UVS3010/UVS3011		315 MHz
Mirage	2014-2015	UVS3010/UVS3011		315 MHz
Montero	2003-2006	UVS3010/UVS3011		315 MHz
Montero Sport	2003-2004	UVS3010/UVS3011		315 MHz
Outlander	2006-2015	UVS3010/UVS3011		315 MHz
Outlander Sport	2011-2015	UVS3010/UVS3011		315 MHz

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Raider	2008-2009	UVS3010/UVS3011		315 MHz
Nissan				
350Z	2003-2009	UVS3010/UVS3011		315 MHz
370Z	2009-2016	UVS3010/UVS3011		315 MHz
Altima	2013	UVS4010/UVS4011		433 MHz
Altima	2013	UVS3010/UVS3011		315 MHz
Altima	2014	UVS4010/UVS4011		433 MHz
Altima	2006-2012	UVS3010/UVS3011		315 MHz
Armada	2005-2016	UVS3010/UVS3011		315 MHz
Cube	2009-2014	UVS3010/UVS3011		315 MHz
Frontier	2003-2016	UVS3010/UVS3011		315 MHz
GT-R	2009-2016	UVS3010/UVS3011		315 MHz
Juke	2011-2015	UVS3010/UVS3011		315 MHz
Leaf	2011-2015	UVS3010/UVS3011		315 MHz
Maxima	2006-2015	UVS3010/UVS3011		315 MHz
Murano	2003-2015	UVS3010/UVS3011		315 MHz
NV1500	2012-2015	UVS3010/UVS3011		315 MHz
NV200	2013-2015	UVS3010/UVS3011		315 MHz
NV2500	2012-2015	UVS3010/UVS3011		315 MHz
NV3500	2012-2015	UVS3010/UVS3011		315 MHz
Pathfinder	2003-2012	UVS3010/UVS3011		315 MHz
Pathfinder	2013-2014	UVS4010/UVS4011		433 MHz
Quest	2004-2015	UVS3010/UVS3011		315 MHz
Rogue	2008-2013	UVS3010/UVS3011		315 MHz
Rogue	2014-2015	UVS4010/UVS4011		433 MHz
Rogue Select	2014-2015	UVS3010/UVS3011		315 MHz
Sentra	2007-2015	UVS3010/UVS3011		315 MHz
Titan	2004-2015	UVS3010/UVS3011		315 MHz
Versa	2007-2015	UVS3010/UVS3011		315 MHz
Versa Hatch-back	2011	UVS3010/UVS3011		315 MHz
Versa Note	2014-2015	UVS3010/UVS3011		315 MHz
Xterra	2003-2015	UVS3010/UVS3011		315 MHz
Pontiac				
G5	2008-2010	UVS3010/UVS3011		315 MHz
G6	2008-2010	UVS3010/UVS3011		315 MHz
G8	2008-2009	UVS3010/UVS3011		315 MHz
Grand Prix	2007-2008	UVS3010/UVS3011		315 MHz
Montana	2008-2009	UVS3010/UVS3011		315 MHz
Solstice	2008-2009	UVS3010/UVS3011		315 MHz
Torrent	2007-2009	UVS3010/UVS3011		315 MHz
Vibe	2008-2010	UVS3010/UVS3011		315 MHz
Porsche				
911	2005-2008		RDE001V21	433 MHz
911	2005-2008		RDE004V21	315 MHz
911	2009-2015	UVS2000	RDE011V21	433 MHz
911	2010-2014		RDE022V21	315 MHz
918 Spyder	2015	UVS2000	RDE011V21	433 MHz
Boxster	2005-2008		RDE001V21	433 MHz
Boxster	2005-2008		RDE004V21	315 MHz
Boxster	2008-2015	UVS2000	RDE011V21	433 MHz
Boxster	2009-2015		RDE022V21	315 MHz
Carrera GT	2004-2006		RDE001V21	433 MHz
Carrera GT	2004-2006		RDE004V21	315 MHz
Cayenne	2003-2006		RDE005V21	433 MHz
Cayenne	2007-2016	UVS2000	RDE011V21	433 MHz
Cayenne	2008-2015		RDE022V21	315 MHz
Cayman	2006-2008		RDE001V21	433 MHz
Cayman	2006-2008		RDE004V21	315 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Cayman	2009-2012	UVS1000	RDE022V21	315 MHz
Cayman	2009-2015	UVS2000	RDE011V21	433 MHz
Macan	2015	UVS4010/UVS4011	RDE018V21	433 MHz
Panamera	2010-2014	UVS1000	RDE022V21	315 MHz
Panamera	2010-2012	UVS2000	RDE011V21	433 MHz
Panamera	2013-2014	UVS4010/UVS4011	RDE018V21	433 MHz
Panamera	2015	UVS2000	RDE011V21	433 MHz
Ram				
1500	2011-2015	UVS4010/UVS4011		433 MHz
2500	2011-2015	UVS4010/UVS4011		433 MHz
3500	2011-2013	UVS4010/UVS4011		433 MHz
3500	2014-2015	UVS4010/UVS4011		433 MHz
C/V	2012-2015	UVS4010/UVS4011		433 MHz
Rolls Royce				
Ghost	2010-2014	UVS4010/UVS4011	RDE012V21	433 MHz
Phantom	2007-2011	UVS2000	RDE008V21	433 MHz
Phantom	2012-2014	UVS4010/UVS4011	RDE012V21	433 MHz
Wraith	2014	UVS4010/UVS4011	RDE012V21	433 MHz
Saab				
9-3	2003-2012	UVS4010/UVS4011		433 MHz
9-4X	2011	UVS3010/UVS3011		315 MHz
9-5	2003-2009	UVS4010/UVS4011		433 MHz
9-5	2010-2012	UVS3010/UVS3011		315 MHz
9-7x	2005-2009	UVS3010/UVS3011		315 MHz
Saturn				
Astra	2008-2009	UVS4010/UVS4011		433 MHz
Aura	2007-2010	UVS3010/UVS3011		315 MHz
Outlook	2007-2010	UVS3010/UVS3011		315 MHz
Sky	2008-2009	UVS3010/UVS3011		315 MHz
Vue	2007-2010	UVS3010/UVS3011		315 MHz
Scion				
iQ	2012-2015	UVS3010/UVS3011		315 MHz
tC	2006-2015	UVS3010/UVS3011		315 MHz
xB	2007-2015	UVS3010/UVS3011		315 MHz
xD	2008-2014	UVS3010/UVS3011		315 MHz
Smart				
Fortwo	2008-2015	UVS4010/UVS4011		433 MHz
SRT				
Viper	2013-2015	UVS4010/UVS4011		433 MHz
Subaru				
B9 Tribeca	2006-2008	UVS3010/UVS3011		315 MHz
BRZ	2013-2015	UVS3010/UVS3011		315 MHz
Forester	2008-2015	UVS3010/UVS3011		315 MHz
Impreza	2015	UVS3010/UVS3011		315 MHz
Legacy	2004-2015	UVS3010/UVS3011		315 MHz
Outback	2004-2015	UVS3010/UVS3011		315 MHz
Tribeca	2008-2014	UVS3010/UVS3011		315 MHz
WRX	2015-2016	UVS3010/UVS3011		315 MHz
XV Crosstrek	2013-2015	UVS3010/UVS3011		315 MHz
Suzuki				
Equator	2009-2010	UVS3010/UVS3011		315 MHz
Equator	2011-2013	UVS3010/UVS3011		315 MHz
Foreza	2007-2008	UVS3010/UVS3011		315 MHz
Grand Vitara	2005-2013	UVS3010/UVS3011		315 MHz
Kizashi	2010-2013	UVS3010/UVS3011		315 MHz
Reno	2007-2008	UVS3010/UVS3011		315 MHz
SX4	2007-2013	UVS3010/UVS3011		315 MHz
XL-7	2005-2006	UVS3010/UVS3011		315 MHz
XL-7	2007-2009	UVS3010/UVS3011		315 MHz

Application Listings

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
Tesla				
Roadster	2008-2010	UVS2000	RDE011V21	433 MHz
Toyota				
4Runner	2003-2015	UVS3010/UVS3011		315 MHz
Avalon	2006-2015	UVS3010/UVS3011		315 MHz
Camry	2015	UVS3010/UVS3011		315 MHz
Camry	2007-2014	UVS3010/UVS3011		315 MHz
Corolla	2007-2015	UVS3010/UVS3011		315 MHz
FJ Cruiser	2007-2014	UVS3010/UVS3011		315 MHz
Highlander	2007-2015	UVS3010/UVS3011		315 MHz
Land Cruiser	2005-2015	UVS3010/UVS3011		315 MHz
Matrix	2007-2014	UVS3010/UVS3011		315 MHz
Prius	2006-2015	UVS3010/UVS3011		315 MHz
Prius C	2012-2015	UVS3010/UVS3011		315 MHz
Prius V	2012-2015	UVS3010/UVS3011		315 MHz
RAV4	2006-2015	UVS3010/UVS3011		315 MHz
Sequoia	2004-2015	UVS3010/UVS3011		315 MHz
Sienna	2007-2015	UVS3010/UVS3011		315 MHz
Solara	2006-2008	UVS3010/UVS3011		315 MHz
Tacoma	2005-2015	UVS3010/UVS3011		315 MHz
Tundra	2005-2015	UVS3010/UVS3011		315 MHz
Venza	2009-2015	UVS3010/UVS3011		315 MHz
Yaris	2007-2015	UVS3010/UVS3011		315 MHz
Volkswagen				
Beetle	2008-2010	UVS3010/UVS3011		315 MHz
CC	2009-2011	UVS3010/UVS3011		315 MHz
CC	2011-2014	UVS4010/UVS4011	RDE013V21	433 MHz
Eos	2007-2015	UVS3010/UVS3011		315 MHz
Golf	2006-2011	UVS3010/UVS3011		315 MHz
GTI	2006-2012	UVS3010/UVS3011		315 MHz
Jetta	2006-2010	UVS3010/UVS3011		315 MHz
Passat	2006-2010	UVS3010/UVS3011		315 MHz
Phaeton	2002-2007		RDE001V21	433 MHz
Phaeton	2002-2006		RDE004V21	315 MHz
Phaeton	2007	UVS2000	RDE011V21	433 MHz
R32	2008	UVS3010/UVS3011		315 MHz
Rabbit	2006-2009	UVS3010/UVS3011		315 MHz
Routan	2009-2010	UVS4010/UVS4011		433 MHz
Routan	2012	UVS4010/UVS4011		433 MHz
Tiguan	2009-2011	UVS3010/UVS3011		315 MHz
Touareg	2014		RDE022V21	315 MHz
Touareg	2002-2007		RDE005V21	433 MHz
Touareg	2007-2014	UVS2000	RDE011V21	433 MHz
Volvo				
C30	2007-2013	UVS4010/UVS4011		433 MHz
C70	2006-2013	UVS4010/UVS4011		433 MHz
S40	2004-2011	UVS4010/UVS4011		433 MHz
S60	2004-2009	UVS3010/UVS3011		315 MHz
S60	2011-2016	UVS4010/UVS4011		433 MHz
S80	2004-2006	UVS3010/UVS3011		315 MHz
S80	2007-2015	UVS4010/UVS4011		433 MHz
V50	2005-2011	UVS4010/UVS4011		433 MHz
V60	2015	UVS4010/UVS4011		433 MHz
V70	2004-2007	UVS3010/UVS3011		315 MHz
V70	2008-2010	UVS4010/UVS4011		433 MHz
XC60	2010-2015	UVS4010/UVS4011		433 MHz
XC70	2004-2008	UVS3010/UVS3011		315 MHz
XC70	2008-2015	UVS4010/UVS4011		433 MHz
XC90	2004-2014	UVS3010/UVS3011		315 MHz

Make/Model	Year	IntelliSens Universal	OE Replacement	Frequency
VPG				
MV-1	2011-2013	UVS3010/UVS3011	RDE016V21/ RDE023V41	315 MHz

OE Replacement Sensors

Huf develops and produces tire pressure monitoring systems for renowned car and truck manufacturers around the world.

Huf provides the market with original replacement sensors in OE quality for all systems supplied to vehicle manufacturers. The replacement tire sensors can be installed directly without configuration, they are automatically detected, identified and registered by the vehicle system. No further steps are necessary.

*Note: Huf OE Replacement Sensors come in a sleep mode to prolong the life of the battery. Sensor must be put under min 23psi pressure for 4 minutes before any readings can be retrieved from the sensor.

PART NO. RDE001V21



Frequency	433 MHz
Application	Alfa Romeo, Audi, Bentley, Ferrari, Maybach, Maserati, Mercedes-Benz, Porsche, Volkswagen

PART NO. RDE002V21



Frequency	433 MHz
Application	BMW

PART NO. RDE003V21



Frequency	433 MHz
Application	BMW, Land Rover

OE Replacement Sensors (Cont.)

PART NO. RDE004V21



Frequency	315 MHz
Application	Audi, BMW, Maybach, Mercedes-Benz, Porsche, Volkswagen

PART NO. RDE005V21



Frequency	433 MHz
Application	Ferrari, Porsche, Volkswagen

PART NO. RDE008V21



Frequency	433 MHz
Application	BMW, Mini

PART NO. RDE009



Frequency	433 MHz
Application	ITEC, Nova Bus, Prevost, Volvo

PART NO. RDE011V21



Frequency	433 MHz
Application	Audi, Bentley, Ferrari, Lamborghini, Maserati, Porsche, Volkswagen

OE Replacement Sensors (Cont.)

PART NO. RDE012V21



Frequency	433 MHz
Application	BMW, Mini, Rolls-Royce

PART NO. RDE013V21



Frequency	433 MHz
Application	Volkswagen

PART NO. RDE014V21



Frequency	315 MHz
Application	Ford, Lincoln, Mazda, Mercury

PART NO. RDE015V21



Frequency	315 MHz
Application	Ford, Lincoln

PART NO. RDE016V21



Frequency	315 MHz
Application	Ford, Lincoln, Mazda, Mercury, VPG

OE Replacement Sensors (Cont.)

PART NO. RDE017V21



Frequency	433 MHz
Application	BMW, Mini

PART NO. RDE018V21



Frequency	433 MHz
Application	Porsche, Volkswagen

PART NO. RDE019V21



Frequency	315 MHz
Application	Hyundai, KIA

PART NO. RDE020V21



Frequency	315 MHz
Application	Hyundai, KIA

OE Replacement Sensors (Cont.)

PART NO. RDE021



Frequency	433 MHz
Application	Mercedes-Benz Truck

PART NO. RDE022V21



Frequency	315 MHz
Application	Audi, Porsche, Volkswagen

PART NO. RDE023V41 (rubber valve)



Frequency	315 MHz
Application	Ford, Lincoln, Mazda, Mercury, VPG

PART NO. RDE027V21



Frequency	433 MHz
Application	BMW, Mini

Huf IntelliSens Universal Sensors

In addition to the OE sensors, Huf has specifically developed a universal sensor of equivalent quality which contains the full OE functionality. IntelliSens universal sensors are available in just a few versions that replace nearly all common OE TPMS sensors. The reduced variations allows for lower inventory requirements and makes it easier to have the sensor you need, when you need it.

Protocols are already installed on the IntelliSens sensor so setting the sensor is easy and fast taking only seconds to set using a TPMS diagnostic tool. With Huf's valve and sensor configuration, you can install the sensors on both OE and Aftermarket rims without a problem, without the issue of working under the rim.

*Note: Valves must be tightened using a torque wrench to 35in.lbs. (4Nm). IntelliSens must be configured using a TPMS tool or it will not register with the vehicle when doing the relearn process.

PART NO. UVS2000



Frequency	433 MHz
Application	Audi, Bentley, BMW, Ferrari, Lamborghini, Maserati, Porsche, Rolls-Royce, Volkswagen

PART NO. UVS3010



Frequency	315 MHz
Application	Acura, Audi, Buick, Cadillac, Chevrolet, Chrysler, Dodge, Ford, Freightliner, GMC, Honda, Hummer, Hyundai, Infiniti, Isuzu, Jaguar, Jeep, Kia, Land Rover, Lexus, Lincoln, Mazda, Mercedes-Benz, Mercury, Mitsubishi, Nissan, Pontiac, Saab, Saturn, Scion, Subaru, Suzuki, Toyota, Volkswagen, Volvo

PART NO. UVS3011



Frequency	315 MHz
Application	Acura, Audi, Buick, Cadillac, Chevrolet, Chrysler, Dodge, Ford, Freightliner, GMC, Honda, Hummer, Hyundai, Infiniti, Isuzu, Jaguar, Jeep, Kia, Land Rover, Lexus, Lincoln, Mazda, Mercedes-Benz, Mercury, Mitsubishi, Nissan, Pontiac, Saab, Saturn, Scion, Subaru, Suzuki, Toyota, Volkswagen, Volvo

Huf IntelliSens Universal Sensors (cont.)

PART NO. UVS4010



Frequency	433 MHz
Application	BMW, Buick, Cadillac, Chevrolet, Chrysler, Dodge, Fiat, Freightliner, Hyundai, Infiniti, Isuzu Jeep, Kia, Lotus, Mercedes-Benz, Mini, Mitsubishi, Nissan, Porsche, Ram, Rolls-Royce, Saab, Saturn, Smart, SRT, Volkswagen, Volvo

PART NO. UVS4011



Frequency	433 MHz
Application	BMW, Buick, Cadillac, Chevrolet, Chrysler, Dodge, Fiat, Freightliner, Hyundai, Infiniti, Isuzu Jeep, Kia, Lotus, Mercedes-Benz, Mini, Mitsubishi, Nissan, Porsche, Ram, Rolls-Royce, Saab, Saturn, Smart, SRT, Volkswagen, Volvo

Valves

PART NO. RDV021



Valve Length	43 mm
Color	Silver
Generation	2

PART NO. RDV027



Valve Length	43 mm
Color	Titanium
Generation	2

PART NO. RDV022



Valve Length	48 mm
Color	Silver
Generation	2

PART NO. RDV028



Valve Length	48 mm
Color	Black
Generation	2

PART NO. RDV023



Valve Length	49 mm
Color	Silver
Generation	2

PART NO. RDV029



Valve Length	48 mm
Color	Titanium
Generation	2

PART NO. RDV024



Valve Length	51 mm
Color	Silver
Generation	2

PART NO. RDV030



Valve Length	49 mm
Color	Black
Generation	2

PART NO. RDV025



Valve Length	56 mm
Color	Silver
Generation	2

PART NO. RDV031



Valve Length	49 mm
Color	Titanium
Generation	2

PART NO. RDV026



Valve Length	43 mm
Color	Black
Generation	2

PART NO. RDV041 (rubber)



Valve Length	41 mm
Color	Black
Screw Torque	11in.lbs

Accessories



VT56 SET - TPMS Diagnostic Tool

The Huf TPMS Diagnostic Tool VT56 is a fully updatable, universal TPMS scan and configuration tool.

Designed to activate all known TPMS sensors. OBD II connector for resetting the ECU.

- High resolution colorful display
- Perfectly balanced housing
- Programs IntelliSens and most all universal sensors in the market
- Updateable using (WLAN, USB or SD Card)
- Regular software updates
- Wireless data storage and report printing
- Tool includes docking-station and wireless printer



VT56 - TPMS Diagnostic Tool

The Huf TPMS Diagnostic Tool VT56 is a fully updatable, universal TPMS scan and configuration tool. Designed to activate all known TPMS sensors.

- Brilliant high resolution colorful display
- Perfect balanced housing
- Programs most all universal sensors, including Huf IntelliSens universal sensor
- Always up-to-date (WLAN, USB and SD-Card capable)
- Regular software updates
- OBD II connection for re-learn procedure



TWS01 Torque Wrench Set

- Torque wrench with 4 Nm fix torque
- Made for all Huf IntelliSens universal sensors and Huf original replacement sensors

Note: Fast and easy assembly based on new fitting concept (on all Generation 2 valves only).

OE Interchange

OE Number	IntelliSens	OE Replacement
185189	RDE001V21	
239298	RDE011V21	UVS2000
99760602101	RDE001V21	
52933-B2100		UVS4010/UVS4011
000 822 3306	RDE001V21	
000 822 3406	RDE004V21	
000 905 0030		UVS4010/UVS4011
000 905 4100		UVS4010/UVS4011
000 905 7200		UVS4010/UVS4011
002 540 6817	RDE004V21	UVS3010/UVS3011
002 540 7917	RDE004V21	UVS3010/UVS3011
002 540 9417		UVS3010/UVS3011
003 540 0217		UVS4010/UVS4011
005 542 2318	RDE001V21	
005 542 2418	RDE004V21	
12768826-BLACK		UVS3010/UVS3011
12768826-GREY		UVS3010/UVS3011
13172567		UVS4010/UVS4011
13227143		UVS4010/UVS4011
13581558		UVS3010/UVS3011
13581559		UVS3010/UVS3011
13586335		UVS3010/UVS3011
13589597		UVS3010/UVS3011
15114379		UVS3010/UVS3011
15122618		UVS3010/UVS3011
15136883		UVS3010/UVS3011
15268606		UVS3010/UVS3011
15921013		UVS3010/UVS3011
15922396		UVS3010/UVS3011
1K0-907-253A		UVS3010/UVS3011
1K0-907-253D		UVS3010/UVS3011
1K0-907-255A		UVS3010/UVS3011
1K0-907-255C		UVS3010/UVS3011
2000680	RDE011V21	UVS2000
20922900		UVS3010/UVS3011
20923680		UVS3010/UVS3011
20964159		UVS3010/UVS3011
224548	RDE004V21	
224549	RDE001V21	
224551	RDE005V21	
22853741		UVS3010/UVS3011
22854866		UVS3010/UVS3011
228887	RDE011V21	UVS2000
23445327		UVS3010/UVS3011
248887	RDE011V21	UVS2000
25758220		UVS3010/UVS3011
25774006		UVS3010/UVS3011
25789964		UVS4010/UVS4011
25920615		UVS3010/UVS3011
28103AG00A		UVS3010/UVS3011
28103AG01B		UVS3010/UVS3011
28103AG01C		UVS3010/UVS3011
28103AJ00A		UVS3010/UVS3011
28103CA000		UVS3010/UVS3011
282189	RDE011V21	UVS2000
30681555		UVS4010/UVS4011
30748991		UVS3010/UVS3011
31200923		UVS3010/UVS3011
31280297		UVS4010/UVS4011
31302096		UVS4010/UVS4011
31341893		UVS4010/UVS4011
36106790054	RDE012V21	UVS4010/UVS4011
36106798872	RDE017V21	UVS4010/UVS4011
36106856209	RDE027V21	UVS4010/UVS4011
36106856227	RDE012V21	UVS4010/UVS4011
36118378681	RDE004V21	
36118378682	RDE002V21	
36146752128	RDE003V21	
36236779490	RDE008V21	UVS2000
36236781847	RDE008V21	UVS2000

OE Number	IntelliSens	OE Replacement
36236786896	RDE022V21	
3AA907275	RDE013V21	UVS4010/UVS4011
3AA907275B	RDE013V21	UVS4010/UVS4011
3AA907275D	RDE013V21	UVS4010/UVS4011
40700-1A00C		UVS3010/UVS3011
40700-1AA0A		UVS3010/UVS3011
40700-1AA0B		UVS3010/UVS3011
40700-1AA0C		UVS3010/UVS3011
40700-1AA0D		UVS3010/UVS3011
40700-1LA0C		UVS3010/UVS3011
40700-1LA0D		UVS3010/UVS3011
40700-1LA0E		UVS3010/UVS3011
40700-1PA0A		UVS3010/UVS3011
40700-3AN0A		UVS3010/UVS3011
40700-3AN0B		UVS3010/UVS3011
40700-3AN1A		UVS3010/UVS3011
40700-3AN1B		UVS3010/UVS3011
40700-3JA0A		UVS4010/UVS4011
40700-3VU0A		UVS4010/UVS4011
40700-4GA0A		UVS3010/UVS3011
40700-CD001		UVS3010/UVS3011
40700-CK002		UVS3010/UVS3011
40700-JA01B		UVS3010/UVS3011
40700-JK00A		UVS3010/UVS3011
40700-JK00B		UVS3010/UVS3011
40700-JK00C		UVS3010/UVS3011
40700-JK00D		UVS3010/UVS3011
40700-JK00E		UVS3010/UVS3011
40700-JK01A		UVS3010/UVS3011
40700-JK01B		UVS3010/UVS3011
4250A030		UVS3010/UVS3011
4250B668		UVS3010/UVS3011
4250B875		UVS3010/UVS3011
4250B877		UVS3010/UVS3011
4250B975		UVS3010/UVS3011
4250D585		UVS3010/UVS3011
42607-06011		UVS3010/UVS3011
42607-06020		UVS3010/UVS3011
42607-0C020		UVS3010/UVS3011
42607-0C070		UVS3010/UVS3011
42607-0E011		UVS3010/UVS3011
42607-30060		UVS3010/UVS3011
42607-33011		UVS3010/UVS3011
42607-33021		UVS3010/UVS3011
42607-35010		UVS3010/UVS3011
42607-52020		UVS3010/UVS3011
42607-75010		UVS3010/UVS3011
42607-AD020		UVS3010/UVS3011
42753-S2A-305		UVS3010/UVS3011
42753-S2A-315		UVS3010/UVS3011
42753-SNA-A81		UVS3010/UVS3011
42753-SNA-A82		UVS3010/UVS3011
42753-SNA-A83		UVS3010/UVS3011
42753-SWA-306		UVS3010/UVS3011
42753-SWA-316		UVS3010/UVS3011
42753-TP6-A82		UVS3010/UVS3011
42753-TR0-A81		UVS3010/UVS3011
42753-TR3-A81		UVS3010/UVS3011
42753-TX6-A81		UVS3010/UVS3011
43130-54J20		UVS3010/UVS3011
43130-54J21		UVS3010/UVS3011
43130-54J22		UVS3010/UVS3011
43130-57L00		UVS3010/UVS3011
43130-78J00		UVS3010/UVS3011
43130-78J10		UVS3010/UVS3011
43130-85Z01		UVS3010/UVS3011
43211-82Z00		UVS3010/UVS3011
43211-82Z10		UVS3010/UVS3011
4D0-907-275A	RDE004V21	
4D0-907-275C	RDE001V21	

OE Interchange (cont.)

OE Number	IntelliSens	OE Replacement
4D0-907-275D	RDE004V21	
4F0-907-275B	RDE011V21	UVS2000
4F0-907-275C	RDE022V21	
4H23-1A-159CB		UVS3010/UVS3011
4H23-1A-159CC		UVS3010/UVS3011
4H23-1A-159CD		UVS3010/UVS3011
4H23-1A-159CE		UVS3010/UVS3011
5096808AA		UVS4010/UVS4011
5127335AB		UVS3010/UVS3011
52088990AC		UVS4010/UVS4011
52933-0W100		UVS3010/UVS3011
52933-1F000		UVS3010/UVS3011
52933-2F000		UVS3010/UVS3011
52933-2G000	RDE019V21	UVS3010/UVS3011
52933-2G200	RDE019V21	UVS3010/UVS3011
52933-2L500		UVS3010/UVS3011
52933-2M000		UVS3010/UVS3011
52933-2M550		UVS3010/UVS3011
52933-2V000		UVS3010/UVS3011
52933-3N000		UVS3010/UVS3011
52933-3N100		UVS4010/UVS4011
52933-3V000		UVS3010/UVS3011
52933-3X200		UVS3010/UVS3011
52933-3X205		UVS3010/UVS3011
52933-4D000	RDE020V21	UVS3010/UVS3011
52933-4D200	RDE020V21	UVS3010/UVS3011
52933-A5000		UVS3010/UVS3011
56029319AA		UVS3010/UVS3011
56029319AB		UVS3010/UVS3011
56029319AC		UVS3010/UVS3011
56029359AA		UVS4010/UVS4011
56029359AB		UVS4010/UVS4011
56029359AC		UVS4010/UVS4011
56029398AA		UVS4010/UVS4011
56029398AB		UVS4010/UVS4011
56029400AB		UVS4010/UVS4011
56029400AC		UVS4010/UVS4011
56029400AD		UVS4010/UVS4011
56029400AE		UVS4010/UVS4011
56029465AA		UVS3010/UVS3011
56029465AB		UVS3010/UVS3011
56029465AC		UVS3010/UVS3011
56029479AA		UVS3010/UVS3011
56029479AB		UVS3010/UVS3011
56053030AA		UVS3010/UVS3011
56053030AB		UVS3010/UVS3011
56053030AC		UVS3010/UVS3011
56053036AA		UVS3010/UVS3011
5L1Z-1A150-AA		UVS3010/UVS3011
5L1Z-1A150-AB		UVS3010/UVS3011
5Q0 907 275	RDE018V21	UVS4010/UVS4011
68001696AA		UVS3010/UVS3011
68001696AB		UVS3010/UVS3011
68001698AA		UVS4010/UVS4011
68001698AB		UVS4010/UVS4011
68038945AA		UVS3010/UVS3011
68078861AA		UVS3010/UVS3011
68157568AA		UVS4010/UVS4011
68157568AB		UVS4010/UVS4011
68239720AA		UVS4010/UVS4011
68239720AB		UVS4010/UVS4011
68239720AC		UVS4010/UVS4011
6F2Z-1A-189A	RDE014V21	UVS3010/UVS3011
6L2A-1A176-AE	RDE014V21	UVS3010/UVS3011
7B0-907-253A		UVS4010/UVS4011
7B0-907-253A		UVS4010/UVS4011
7B0-907-253C		UVS4010/UVS4011
7L0-907-275	RDE005V21	
7L0-907-275B	RDE005V21	
7L1Z-1A-189A	RDE014V21	UVS3010/UVS3011

OE Number	IntelliSens	OE Replacement
7PP-907-275	RDE011V21	UVS2000
7PP-907-275B	RDE011V21	UVS2000
7PP-907-275D	RDE011V21	UVS2000
7PP-907-275E	RDE022V21	
7PP-907-275F	RDE011V21	UVS2000
7PP-907-275G	RDE022V21	
8257740060		UVS3010/UVS3011
8651700		UVS3010/UVS3011
88974915		UVS3010/UVS3011
8C2A-1A176-AA	RDE015V21	UVS3010/UVS3011
8C2T-1A150-AA	RDE015V21	UVS3010/UVS3011
8C2T-1A150-BA	RDE015V21	UVS3010/UVS3011
8C2Z-1A189-A	RDE015V21	UVS3010/UVS3011
92186507		UVS4010/UVS4011
95536166100	RDE005V21	
95560602100	RDE011V21	UVS2000
95560602300	RDE022V21	
99760602100	RDE001V21	
99760602120	RDE011V21	UVS2000
99760602301	RDE004V21	
99760602302	RDE004V21	
99760602321	RDE022V21	
9L3T-1A-150BD	RDE016V21/RDE023V41	UVS3010/UVS3011
9L3T-1A-150BE	RDE016V21/RDE023V41	UVS3010/UVS3011
9L3T-1A-180AB	RDE016V21/RDE023V41	UVS3010/UVS3011
9L3T-1A-180AC	RDE016V21/RDE023V41	UVS3010/UVS3011
9L3T-1A-180AD	RDE016V21/RDE023V41	UVS3010/UVS3011
9L3T-1A-180AE	RDE016V21/RDE023V41	UVS3010/UVS3011
9L3T-1A-180AF	RDE016V21/RDE023V41	UVS3010/UVS3011
9L3T-1A-180BA	RDE016V21/RDE023V41	UVS3010/UVS3011
9L3Z-1A-189A	RDE016V21/RDE023V41	UVS3010/UVS3011
AD43-360671-AA	RDE011V21	UVS2000
AD43-360671-BA	RDE022V21	
BBM2-37-140		UVS3010/UVS3011
BBM2-37-140A		UVS3010/UVS3011
BBM2-37-140B		UVS3010/UVS3011
BHA4-37-140		UVS3010/UVS3011
C2C25519		UVS3010/UVS3011
C2C40476		UVS3010/UVS3011
C2C41656		UVS3010/UVS3011
C2D21601		UVS3010/UVS3011
C2Z15017		UVS3010/UVS3011
CD23-360671-AA	RDE011V21	UVS2000
CD23-360671-BA	RDE022V21	
CM5T-1A150-AA	RDE016V21/RDE023V41	UVS3010/UVS3011
DE8T-1A180-AA	RDE016V21/RDE023V41	UVS3010/UVS3011
DR3Z-1A189-A		UVS3010/UVS3011
F2GZ-1A-189A		UVS3010/UVS3011
GN3A-37-140B		UVS3010/UVS3011
LR003135		UVS3010/UVS3011
LR010533		UVS3010/UVS3011
LR010537		UVS3010/UVS3011
LR018859		UVS3010/UVS3011
LR018860		UVS3010/UVS3011
LR032833		UVS3010/UVS3011
LR032836		UVS3010/UVS3011
LR0500461		UVS3010/UVS3011
MN103033		UVS4010/UVS4011
MN103081		UVS3010/UVS3011
RQH500121		UVS3010/UVS3011
RQH500122		UVS3010/UVS3011
RQH500460		UVS3010/UVS3011
RQH500461		UVS3010/UVS3011
XR855950		UVS3010/UVS3011
YDB000060	RDE003V21	
ZZC1-37-140	RDE014V21	UVS3010/UVS3011
ZZDA-37-140	RDE016V21/RDE023V41	UVS3010/UVS3011
GN3A-37-140		UVS3010/UVS3011
GN3A-37-140A		UVS3010/UVS3011
YDB000061	RDE003V21	

Huf North America

Automotive Parts Manufacturing, Corp.
9020 W. Dean Road
Milwaukee, WI 53224, USA
Tel.: +1 414-365-8175
E-mail: info_us@intellisens.com

Technical Questions: 1-855-HUF-TPMS or huf@tpmssupport.com



www.huf-group.com



www.intellisens.com

